

SAFETY NOTICE

GSK Consumer Healthcare Requests that Consumers Check Bottles for Holes in Five Excedrin Brands (Potential Failure to Meet Child Resistant Packaging Requirement)



HAZARD: If the bottle has a hole in the bottom that is large enough, children could access and swallow the contents, posing a potential safety risk.

PRODUCT: Certain lots of Excedrin Migraine Caplets, Excedrin Migraine Geltabs, Excedrin Extra Strength Caplets, Excedrin PM Headache Caplets, and Excedrin Tension Headache Caplets in large-sized bottles (50 count & above).

Please visit www.excedrin.com for a list of impacted lot #'s and additional information. Products currently available in stores are not impacted by this notice.

REMEDY: Consumers should examine their plastic bottles for holes, especially near the bottom. If such a condition is found, please contact GSK Consumer Healthcare:

1-800-468-7746

Monday – Friday, 8:00am – 6:00pm EST

This safety notice is being issued in cooperation with the US Consumer Product Safety Commission (CPSC).

Post Until April 23, 2021